

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,877,394 B2  
DATED : April 12, 2005  
INVENTOR(S) : Massey et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11.

Line 51, "pedal support having" should be -- pedal support portion having --.

Line 53, "being coupled" should be -- being pivotally coupled --.

Line 53, "lower" should be -- lower segment --.


Line 54, "about pivot" should be -- about a pivot --.

Column 16.

Line 12, "pedal" should be -- a pedal --.

Signed and Sealed this

Fourteenth Day of February, 2006



JON W. DUDAS  
Director of the United States Patent and Trademark Office